


Exit Reason Details

1 - Auto Mode min delivery

Auto Mode was at minimum delivery for 2:30 hours. BG was required to continue in Auto Mode.

2 - Sensor Updating

Auto Mode exit due to SG not available. Sensor was trying to update, and recovery did not occur within 90 minutes.




Thursday 20/06

TDD 16.9U

Total Basal 47% | 7.9U

Total Bolus 53% | 9U

Time in Range




Thursday 27/06

TDD 20.7U


Total Basal 43% | 8.9U

Total Bolus 57% | 11.8U

Time in Range



*Active insulin considered



Representative patient profile.